

# Product Change Notification

Tel: +886 7 8217000

Date: 2022.03.30

Dear Sirs & Madams,

Please be informed that the following technical changes will be implemented to the products you are currently purchasing.

1. Contents of Change

Item	Current	New	
LED driver	Renesas (P/N: ISL97678IRZ)	Rohm (P/N: BD93941EFV)	

### 2. Product

Part Name		Revision		Implement
		Current	New	schedule
6.4"	TX16D201VM0BAB	Α	В	Jul. 2022
7.0	TX18D205VM0BAA, TX18D205VM0BPA, TX18D205VM0BXA/BYA	С	D	Aug. 2022
	TX18D210VM0BAA, TX18D210VM0BPA, TX18D210VM0BXA/BYA	А	В	
7.0	TX18D206VM0BAA, TX18D206VM0BPA, TX18D206VM0BXA/BYA	С	D	Sep. 2022
	TX18D211VM0BAA, TX18D211VM0BPA, TX18D211VM0BXA/BYA	А	В	
7.0"	TX18D212VM0BAA	А	В	Aug. 2022
10.1"	TX26D202VM0BAA TX26D202VM0BYA	C A	D B	Jul. 2022
12.3"	TX31D200VM0BAA TX31D200VM0BXA	C B	D C	Sep. 2022

## 3. Reason of Change

L/T of current IC supplier (Renesas) becomes unreliable because of global shortage, the alternative one (Rohm) is sourced and qualified to stabilize our product supply.

## 4. Impact on Product Specification

Product optical performance and other electronic specification remains unchanged, PCBA dimension change are detailed in Note-1 & Note-2.

### 5. Schedule

We plan to introduce the Rohm LED driver as indication above. However, we will continue sourcing Renesas IC as the backup. Dual source shall be applied in order to stabilize the L/T, and sustain our supply.

In case of further questions, please contact your sales representative. Thank you.

Proposed by: <u>Ub/ack</u> Oblack Tsai / Senior Manager


LCM Design Section

Engineering Development Dept.

PCN No.: 1042 Page: 1/1

2-2, East 13th St. K.E.P.Z. Kaohsiung, Taiwan 806, ROC.

Tel: +886 7 8217000



PCN No.: 1042 Page: 2/2