PCN_RD140008

Dear Customer

We have been advised by Titan Opto the following design change is being applied to the part numbers shown below with immediate effect. The reason for this change is to improve the PCB placement process where optical inspection is used. No electrical or mechanical change so form, fit and function are not affected.

Anglia operates a strict FIFO system in our Distribution Centre facility, therefore it may take some time for this change to filter through to customer deliveries of the below part number(s).

Please make the relevant person(s) in your organisation aware of this change.

TOL2012DWF	TOL2012MGB	TOL2012MR
TOL2012MG	TOL2012MGB	TOL2012MRA
TOL2012MG	TOL2012MO	TOL2012MRB
TOL2012MGB	TOL2012MOB	TOL2012MRB
TOL2012MGB	TOL2012MR	TOL2012MRB
TOL2012MGB	TOL2012MR	TOL2012MY

Visual appearance of PCB Front side of 41PCB	Front side of 43PCB	Front side of 43PCB with zener	
Before Change			
After Change			
A mark is added to the front side. The back side is unchanged.			
Impact of Change: Visual appereance	difference.		

Sincerely

Anglia Components Ltd