

ID No. 297	<b>Product/Process Change Notification</b>	Date 13.03.2015
<b>Product</b>	PCS3 rel2	
<b>Ordering Code</b>	L30960-N3500-A200 L30960-N3510-A200	
	Ordering No. changes: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
	New Ordering Code:	

**Reason of Change:**

- |   |  |
|---|--|
| <input type="checkbox"/> Technical requirement          | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement           | <input type="checkbox"/> Location of production moved                    |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other:  |

<b>Description of change:</b>	<p>This new firmware version improves PCS3 under certain conditions. Particularly</p> <ul style="list-style-type: none"> <li>• Internet services, Missing TCP data if read buffer is filled up to the 15K byte limit</li> <li>• Power saving &amp; Power on/off, RTS0 does not wake module</li> <li>• AT Command, Wrong threshold of Overvoltage shutdown</li> <li>• AT Command, URC: Undervoltage and Overvoltage are not displayed</li> </ul> <p>Have been fixed / are improved</p> <p>This application related change is not approval relevant.</p> <p>The application revision string of SW 02.100 is ARN = 01.000.02</p>
<b>Scheduled date of introduction (cw/year):</b>	Week commencing Mar 16 <sup>th</sup> 2015
<b>Timing note:</b>	-

<b>Quality assurance measurements:</b>	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.
--	---

<b>Product Lifecycle Manager/Name:</b>	Frank Ryll
<b>Signature:</b>	<i>i.v. F. Ryll</i>
<b>Quality Management/Name:</b>	Jörg Erdmann
<b>Signature:</b>	<i>i.v. J. Erdmann</i>

**Attachments:**

-