

knitter-switch

Product Change Notification

Products affected: DBS 3001, 3002, 3003, 3004, 3005, 3006, 3007, 3008, 3009, 3010, 3012 with and without suffix „THR“

DBS 3101, 3102, 3103, 3104, 3105, 3106, 3107, 3108, 3109, 3110, 3112 with and without suffix „THR“


DBS 3102 THR WI

Effective date: Production month November 2011


Details:

Due to a problem with the document management a change of the part geometry wasn't entered on time into several of the 3000 series data-sheets.

The modification concerns the height of cover, the distance to the PCB surface and the length of terminals.



Until October 2011



From November 2011

knitter-switch, June 2013

Oliver Kluj
Technical Director