

ID No. 883	Product/Process Change Notification	Date 13.04.2022
Product	Ordering Code	
BGS12 Rel. 2	L30960-N5500-A201	
Ordering Code changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Product	New Ordering Code	

Reason of Change:

- | | |
|---|--|
| <input checked="" type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	The new firmware improve the overall system performance of the product e.g. in regards of low boot voltage. For more details please check corresponding release note "bgs12_rn_v02000a.pdf" All the changes are not approval relevant. - SW revision is 02.000 - ARN is 01.000.09
Availability of SW :	CW15/2022
Availability of modules ex warehouse:	Q3/2022
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES assumes that the customer agrees to the change.
Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.

Attachments: no

2022/4/18

19.04.2022

X WANG JIANFENG

Product Program Manager
Signed by: WANG Jianfeng

X 

Vice President Quality Management
Signed by: ERDMANN Joerg