

Product Change Notice

Impact Model No. or Part No.:

PCM-3363D-1GS8A1E

PCM-3363N-1GS6A1E

PCM-3363Z-1GS6A1E

PCM-3363Z2-1GS6A1E

(T-PN will be informed by region)

Reason for Change:

PCM-3363 clock gen 1410023557-01 was EOL due to manufacture process change. PCM-3363 will implement new clock gen 1410025828-01 and BIOS will be updated to V2.01 1420037531.

Change List:

	Before	After
Component	1410023557-01	1410025828-01
PCB	No change	
BIOS	1420028826 V1.10	1420037531 V2.01 Due to not backward compatible, new revision starts from V2.01 to distinguish
Driver	No change	

Related Document:

Clock gen EOL letter:



MS950QA1410-03_(
PUNCH=C2=E0SAW

New clock gen datasheet:



1410025828-01-SPE
C.pdf

Benefits or Impacts:

1410025828-01(new clock gen) is only compatible with BIOS V2.01 and 1410023557-01(old clock gen) is only compatible with BIOS V1.10. BIOS RD tried to make BIOS V2.01 backward compatible, but in vain, and SOM has similar case. Please PSM inform local AE and RMA.

ADVANTECH**Effective Date:****Shipment after 21st, Nov., 2015****Ordering Information:**

Finished goods PN has no change

Early sample for testing if needed:

Ordering PN for testing	Mapping PN
PCM3363N1GS6A1E-ES	PCM-3363N-1GS6A1E
PCM3363D1GS8A1E-ES	PCM-3363D-1GS8A1E

Issue Date	14 th , Sep., 2015	Issue by	PM: Austin Lo
-------------------	-------------------------------	-----------------	---------------