	HF115F/HF115F-Q Product packaging change	Versions: 2
	PMI_20200707	Page 1 / of 3

Subject of Change

Notice on packaging changes for HF115F/XX Family & HF115F-Q Family

Affected Products

Complete HF115F/xx Family


Complete HF115F-Q Family

Reason for Change


Improve protection for relays - blister and tube packaging.

Change detail:


HF115F Blister changes:



1. Change the structure of under-cut.
2. Increase horizontal reinforcing ribs around blister tray.


	HF115F/HF115F-Q Product packaging change	Versions: 2
		Date: 24.06.2020
	PMI_20200707	Page 2 / of 3

HF115FQ - Blister of HF115FQ with horizontal QC terminals





For the customer's convenience to take out the relay from the plastic tray, HF115F-Q horizontal type consists of a plastic tray + plastic bag. The packaging of the carton is changed to the packaging of the upper and lower plastic trays to the cover (same as HF115F-Q vertical). Number of packages.

The quantity remains unchanged, the outer box size, and the plastic tray size changes as shown in the above figure.

	HF115F/HF115F-Q Product packaging change	Versions: 2
		Date: 24.06.2020
	PMI_20200707	Page 3 / of 3

Blister tray of HF115FQ with vertical QC terminals:

Before change	After change
	

To remove the relay easily from the plastic tray, the HF115F-Q vertical plastic tray structure is fine-tuned. The external dimensions remain unchanged and the number of packages remains unchanged.

Time Schedule for Change:

September 2020 – Hongfa production start