

Product Change Notification:

Reference: PCNMK1002

Affected Part Numbers:

1400 Series:

| | | | | | |
|----------|----------|----------|----------|----------|----------|
| 1410313C | 1410460C | 1430433C | 1468422C | 1422512C | 1468507C |
| 1415312C | 1410478C | 1430450C | 1468431C | 1422514C | 1468508C |
| 1422311C | 1415440C | 1433428C | 1410516C | 1433507C | 1410604C |
| 1433393C | 1415449C | 1433433C | 1410517C | 1433510C | 1410605C |
| 1447383C | 1415465C | 1433445C | 1410524C | 1433512C | 1410606C |
| 1447385C | 1422435C | 1447423C | 1415513C | 1447506C | 1415604C |
| 1468362C | 1422441C | 1447427C | 1415514C | 1447508C | 1415605C |
| 1468373C | 1422455C | 1447440C | 1415517C | 1447509C | 1422604C |
| 1410454C | 1430430C | 1468420C | 1422509C | 1468505C | |

Description of the Change:

The winding direction has been changed from clockwise to counter-clockwise.

Potential Product Performance / Behavior Impact:

No changes to form, fit, or function as per the datasheet specification. The electrical specification of the product has not changed.

Effective date of shipment of changed parts:

All parts with 'G' prefix date codes were wound in a clockwise direction, production of which has now ceased.

All parts with 'D' prefix date codes are wound in a counter-clockwise direction, production of which commenced wk38 of 2014.



Certificate No. FM 13273 / EMS 92499