

3rd June, 2022

To: Valued Customer

From: Littelfuse Product Management

Subject: Immediate EOL of certain Cartridge fuses

As regards to the above reference, due to low/zero volumes, product rationalization and other reasons, Littelfuse will be phasing out the following parts with immediate effect;

- 322 series : 1A to 10A inclusive
- 876 series : 250mA
- 285 series : 125mA to 20A inclusive

We will not be able to support any new orders going forward.

As regards to existing open orders in the system today, please see below feedback;

- 322 series : will support
- 876 series, specifically only 0876.250xxx : will support
- 285 series : No orders in system

Part numbers affected are shown on the next page.

Please let us know should you have further queries.

Yours sincerely,

Style Liu
Global Product Manager
SLiu@Littelfuse.com
Tel - +86 512 67613189-2251

Affected Part numbers

332 Series		876 series	285 series
0332001.HXP	J332001.MXP	0876.250MXEP	0285.125MXRP
0332001.MXP	J332002.MXP	0876.250MRET1P	0285.315MXRP
0332001.VXP	J332003.MXP	0876.250MRT1P	0285.500MXRP
0332002.HXP	J332004.MXP		0285001.MXRP
0332002.MXP	J332005.MXP		028501.6MXRP
0332002.VXP	J332006.MXP		0285002.MXRP
0332003.HXP	J332007.MXP		028502.5MXRP
0332003.MXP	J332008.MXP		02853.15MXRP
0332003.VXP	J332009.MXP		0285005.MXRP
0332004.HXP	J332010.MXP		028506.3MXRP
0332004.MXP	J3321.25MXP		0285008.MXRP
0332004.VXP			0285010.MXRP
0332005.HXP			0285015.MXRP
0332005.MXP			0285020.MXRP
0332005.VXP			0285.125HXP
0332006.HXP			0285.315HXP
0332006.MXP			0285.500HXP
0332006.VXP			0285001.HXP
0332007.HXP			028501.6HXP
0332007.MXP			028502.5HXP
0332007.VXP			02853.15HXP
0332008.HXP			0285005.HXP
0332008.MXP			028506.3HXP
0332008.VXP			0285008.HXP
0332009.HXP			0285010.HXP
0332009.MXP			0285015.HXP
0332009.VXP			0285020.HXP
0332010.HXP			0285002.HXP
0332010.MXP			
0332010.MXPN			
0332010.VXP			
03321.25HXP			
03321.25MXP			
03321.25VXP			