gemalto

ID No. 00547a	Product/Process Change Notification	Date 06.07.2018
Product	**Ordering Code**	
PH8 REL.3.3	L30960N1900A330	
PH8 CI REL.3.3	L30960N1905A330	
PH8-P REL.3.3	L30960N1910A330	
PH8-P CI REL.3.3	L30960N1915A330	
PHS8-E REL.3.3	L30960N2440A330	
PHS8-P CI REL.3.3	L30960N2415A330	
PHS8-P REL.3.3	L30960N2410A330	
PHS8-US CI REL.3.3	L30960N2405A330	
PHS8-US REL.3.3	L30960N2400A330	
PHS8-USA CI REL.3.3	L30960N2425A330	
PHS8-USA REL.3.3	L30960N2420A330	
PXS8 CI REL.3.3	L30960N2605A330	
PXS8 H REL.3.3	L30960N2630A330	
PXS8 I REL.3.3	L30960N2610A330	
PXS8 REL.3.3	L30960N2600A330	
PXS8 S REL.3.3	L30960N2620A330	
Ordering Number changes:	☐ Yes ☒ No	

Reason of Change:

☐ Technical requirement
☐ Customer requirement
☒ Quality improvement

☐ Change of production process/logistical changes
☐ Location of production moved
☐ Other:

Description of change:	Gemalto M2M would like to inform customers of a new software that improves the stability of the above mentioned product variant including: - Bootloader update to improve the flash memory management - Improvement on (U)SIM Application Toolkit commands - Improvement on SMS related "CMS ERROR" codes - Improvement on GPS function in some provinces in China SW Revision is same with previous one, i.e.: **03.320** The application revision string of **ARN is changed from 01.000.06 to 01.000.15** **This application related change is not approval relevant.**
Scheduled date of introduction (cw/year):	- Availability of SW: **CW28 2018** - Start of first shipments ex warehouse: depends on the product, as listed below.

gemalto

Product	Order Nb.	Start of first shipments ex warehouse: (2018)
PH8 REL.3.3	L30960N1900A330	not before CW36
PH8 CI REL.3.3	L30960N1905A330	not before CW36
PH8-P REL.3.3	L30960N1910A330	not before CW36
PH8-P CI REL.3.3	L30960N1915A330	not before CW36
PHS8-E REL.3.3	L30960N2440A330	not before CW36
PHS8-P CI REL.3.3	L30960N2415A330	not before CW36
PHS8-P REL.3.3	L30960N2410A330	not before CW36
PHS8-US CI REL.3.3	L30960N2405A330	not before CW36
PHS8-US REL.3.3	L30960N2400A330	not before CW36
PHS8-USA CI REL.3.3	L30960N2425A330	not before CW36
PHS8-USA REL.3.3	L30960N2420A330	not before CW36
PXS8 CI REL.3.3	L30960N2605A330	not before CW36
PXS8 H REL.3.3	L30960N2630A330	not before CW36
PXS8 I REL.3.3	L30960N2610A330	not before CW36
PXS8 REL.3.3	L30960N2600A330	not before CW37
PXS8 S REL.3.3	L30960N2620A330	not before CW36

Please note that a SW downgrade to earlier SW is not supported and could cause damage of the module!

Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto will M2M GmbH assume that the customer agrees to the change.

Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.

09.07.2018

11.07.2018

X ⎯⎯⎯⎯⎯⎯⎯⎯

X i.V. ⎯⎯⎯⎯⎯⎯⎯⎯

Ganda WIJAYA
Product Lifecycle Manager
Signed by: Wijaya Ganda 172390
Attachments: -

Jörg Erdmann
Vice President Quality Management