1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	012	0000002391	See list below	Appliance Outlet	5091	





*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected						
6182.0001	6182.0002	6182.0003	6182.0004	6182.0005	6182.0006	6182.0007
6182.0008	6182.0034	6182.0037	6182.0039	6182.0040	6182.0045	6182.0046
6182.0050						

2 Type of change

Change of approval and rating markings on the moulding body.

3 Detailed description of change

Old product appearance	New product appearance
	
Old product appearance	New product appearance
Flange with through holes special type	
	

Please note that only rivet-on mounting types and special type are ilustrated. However, the same changes apply to both mounting types with screw flange as listed in the affected part numbers list in chapter 1.

4 Reason of change

Standards update according to the new UL/CSA 60320-1

5 Release date

The change will be rolled out starting ww 43/2019 (Date code 1943 or higher on packaging label) and lasts approx. 6 months depending on the variant. This change has no effect on the validity of the approval certificates.

6 Impact of change and recommended action

Form	Yes	Change of approval marks and rating.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
5091 Data Sheet	