1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
80	084	002	0000006149	See list below	800840020000006149	FSW-130	
80	084	002	0000006152	See list below	800840020000006152	FMBB	
80	084	002	0000006511	See list below	800840020000006511	FMCB	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected				
5500.2219	5500.2220	5500.2221	5500.2222	
5500.2219.01	5500.2281			

2 Type of change

- Nickel plated case instead of aluminium case
- Different shape of external quick connect terminals
- Changed ground terminal position


3 Detailed description of change

- Change of product appearance due to new nickel plated case instead of aluminium case and different shape of plastic part for quick connect terminals see photo below
- Different shape of plastic part for external quick connector terminals
- Position of earth terminal


Old product appearance (example)	New product appearance (example)
	
	

Old mechanical drawing

Case MB with quick connect terminals




New mechanical drawing




Old mechanical drawing

Case MB with screw terminals



New mechanical drawing



4 Reason of change

- Reorganization of production process

5 Release date

The change will be rolled-out starting 27/2021 and lasts approx. 12 months depending on the variant.
The change takes effect in 27/2021.

6 Impact of change and recommended action

Form	Yes	New material and different quick connect terminals
Fit	Yes	Earth terminal position
Function	No	No change in function
Manufacturing	No	No change of production site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks