gemalto

ID No. 00399	**Product/Process Change Notification**	Date 16 June 2016

Product	**Ordering Code**
BGS5	**L30960N3300A100**
Ordering No. changes:	☐ Yes ☒ No
New Ordering Code:	

Reason of Change:

☐ Technical requirement ☐ Change of production process/logistical changes

☐ Customer requirement ☐ Location of production moved

☒ Quality improvement ☐ Other:

Description of change:	Gemalto M2M would like to inform customers of a new firmware (FW) and Cinterion Mobility Toolkit (CMTK). This new firmware stabilizes a reset issue related to a memory incompatibility found in March time frame after introduction of a new memory to the module. The introduction of the new component was due to an end of life of the old one. With this adapted firmware we are able to restart factory production. In addition to the stabilization we also have minor updates to the JRC and CMTK. A Release Note (BGS5_rn_v01100c) describes the issues in greater details. When ordering, please specify part number L30960N3300A100 and Batch Number 12 to ensure quick processing. This application related change is not approval relevant. The application revision string of SW 01.100 is ARN = 00.000.21
Scheduled date of introduction (cw/year):	CW 26/2016
Timing note:	This Change Notification is information only. A customer confirmation is not necessary.

Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.

6/16/2016   16.06.2016

X Peter Shaffer

Peter Shaffer
Product Manager
Signed by: Peter Shaffer 10022570

X i. Jörg Erdmann

Jörg Erdmann
Vice President Quality Management
Signed by: Joerg Erdmann 10015214

Attachments:
-