gemalto

ID No. 00579	**Product/Process Change Notification**	Date 3rd September 2018

Product	**Ordering Code**
BGS2-E Rel.4	**L30960N2200A400**
BGS2-W Rel.4	**L30960N2210A400**
Ordering No. changes:	☐ Yes ☒ No
New Ordering Code:	

Reason of Change:

☐ Technical requirement

☐ Customer requirement

☒ Quality improvement

☐ Change of production process/logistical changes

☐ Location of production moved

☐ Other:

Description of change:	Gemalto introduce with this release following improvements: - Bearer Independent Protocol capability - HTTP post session behaviour - several minor modifications to improve the overall system stability The new software can be identified by ARN 01.000.22. In addition Gemalto has modified the average ramp-down rate in soldering profile in updated HID valid for all BGS2 variants. For details on all changes please refer to corresponding RN.
Scheduled date of introduction (cw/year):	Cw42 2018 RN, documentation and software are available upon request.
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.

03.09.2018

03.09.2018

X _i.V. R. Dimai_

X _i. Jörg Erdmann_

Armin Dimai
Product Lifecycle Manager IoT
Signed by: Armin Dimai 10015210

Jörg Erdmann
Vice President Quality management IoT
Signed by: Joerg Erdmann 10015214

Attachments:
‒