



Product Discontinuance Notice - PDN 21_0102 Rev. A

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of Leaded manufacturing process for HS ADCs

Publication Date: 29-Mar-2022

Last Time Buy Date: 28-Jun-2022

Last Time Ship Date: 28-Jun-2023

Revision Description:

Removing all generics.

Reason For Discontinuance

Discontinuance of Leaded manufacturing process

Comments

Discontinuance of Leaded manufacturing process

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

| | | | | | |
|------------------|-------------------------|----------------------|-----------------------|---------------|----------------------|
| Americas: | PDN_Americas@analog.com | Europe: | PDN_Europe@analog.com | Japan: | PDN_Japan@analog.com |
| | | Rest of Asia: | | | PDN_ROA@analog.com |

PDN 21_0102 Discontinued Parts Material List

Removed Parts Across All Revisions of PDN 21_0102 Notices

| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
|-----------------|----------------|------------------|-----------------------|------------------------------------|
| AD6634BBC | AD6634 | AD6634BBCZ | Yes | Replacement part is RoHS Compliant |
| AD6650ABC | AD6650 | AD6650ABCZ | Yes | Replacement part is RoHS Compliant |
| AD6650ABC-REEL | AD6650 | AD6650ABCZ-REEL | Yes | Replacement part is RoHS Compliant |
| AD9129BBC | AD9129 | AD9129BBCZ | Yes | Replacement part is RoHS Compliant |
| AD9129BBCRL | AD9129 | AD9129BBCZRL | Yes | Replacement part is RoHS Compliant |
| AD9625BBP-2.5 | AD9625 | AD9625BBPZ-2.5 | Yes | Replacement part is RoHS Compliant |
| AD9625BBP-2.6 | AD9625 | AD9625BBPZ-2.6 | Yes | Replacement part is RoHS Compliant |
| AD9625BBPRL-2.5 | AD9625 | AD9625BBPZRL-2.5 | Yes | Replacement part is RoHS Compliant |
| AD9625BBPRL-2.6 | AD9625 | AD9625BBPZRL-2.6 | Yes | Replacement part is RoHS Compliant |
| AD9739BBC | AD9739 | AD9739BBCZ | Yes | Replacement part is RoHS Compliant |
| AD9739BBCRL | AD9739 | AD9739BBCZRL | Yes | Replacement part is RoHS Compliant |

Appendix A - PDN 21_0102 Revision History

| Rev | Publish Date | Rev Description |
|------------|---------------------|------------------------|
| Rev. - | 28-Jun-2021 | Initial Release |
| Rev. A | 29-Mar-2022 | Removing all generics. |

Analog Devices, Inc. Proprietary Information

DocId:1809 Layout Rev:3 Parent DocId:None