



PRODUCT CHANGE NOTIFICATION

MAGNETICS



Bourns® SRF1260 and SRF1280 Series Dual-Winding Shielded Power Inductors

Assembly, Process and Gluing Changes


Riverside, California –March 18, 2025 – In the spirit of continuous improvement, effective September 29, 2025, Bourns will change its assembling and gluing processes from manual to automated for the [SRF1260](#) and [SRF1280](#) Series Dual-Winding Shielded Power Inductors. The type of glue and its application position will also be changed to enhance durability. The new glue supplier has been qualified and is included in the Bourns Authorized Vendor List. Additionally, the copper wire color will be changed from gold and red to gold only. A list of affected part numbers is included below.

Affected Part Numbers					
SRF1260-R47Y	SRF1260-100M	SRF1260-151M	SRF1280-1R0Y	SRF1280-150M	SRF1280-221M
SRF1260-1R0Y	SRF1260-150M	SRF1260-221M	SRF1280-1R5Y	SRF1280-220M	SRF1280-331M
SRF1260-1R5Y	SRF1260-220M	SRF1260-331M	SRF1280-2R2Y	SRF1280-330M	SRF1280-471M
SRF1260-2R2Y	SRF1260-330M	SRF1260-471M	SRF1280-3R3Y	SRF1280-470M	SRF1280-681M
SRF1260-3R3Y	SRF1260-470M	SRF1260-681M	SRF1280-4R7Y	SRF1280-680M	SRF1280-821M
SRF1260-4R7Y	SRF1260-680M	SRF1260-821M	SRF1280-6R8Y	SRF1280-820M	SRF1280-102M
SRF1260-6R8Y	SRF1260-820M	SRF1260-102M	SRF1280-8R2Y	SRF1280-101M	
SRF1260-8R2Y	SRF1260-101M	SRF1280-R47Y	SRF1280-100M	SRF1280-151M	

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC25029



As shown in the images above, the form of the affected part numbers will change slightly due to the change in gluing position. The fit and function of the affected inductors will remain the same. The quality and reliability of the affected inductors should be improved as a result of the changes. Traceability will be maintained through lot code and date code.

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications for verification of satisfactory performance.

Implementation dates are as follows:

Date that deliveries of products manufactured using the current assembly, processes and glue will cease: **September 28, 2025**

Date that deliveries of products manufactured using the new assembly, processes, and glue will begin: **September 29, 2025**

First date code using the above changes: **2540**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).