SUBJECT: Notice of Lead free for EMIFILâ due to revision of RoHS exemption in January 2013

Dear Sir and madam,

Thank you very much for your patronage on our products.

Please be advised that we would like to change the material in ceramic to LF free, to eliminate the harmful material in environment with regard to below applicable products.

The Lead free products will be our standard from now onwards, and the present products including Pb in ceramic will be discontinued.

1. Applicable Products

EMIFIL ® (LC Combined type) NFE31PT222 series, NFE61PT472 series

• EMIFIL ® (LC Combined Array type) NFA31GD470series

BLOCK TYPE EMIFIL® BNX(002/003/005/012/016/022/102) series,

BNP(002/003) series

FEED-THRU type ceramic capacitor DF40N(C21/C81/Y81)H332 series

DF41NY81H332 series

Murata Part number is not changed. Please refer to Part No List on page 2.

2. Reason of change

- -We will accomplish Lead free to eliminate the harmful material in environment.
- -RoHS exemption No.7-(c) III "Lead in dielectric ceramic in capacitors for a rated voltage of less than 125 V AC or 250 V DC" will be abolished in Jan., 2013. As the above mentioned products has been applied this exemption, we will switch to new Lead free products in compliance with new RoHS instead of them.

3. Quality

- -The electrical performance / characteristics of new product are the same as present type.
- -There is no change in specification.

4. Schedule

Last order: by the end of Feb, 2012 End of Production: by the end of Jun, 2012

The date of starting shipment of new type from Jul., 01, 2012

5. Request to you

Please feel free to contact with us if you have any special inquiry and/or questions. If we do not receive any reply or requests from you **by the end of Feb., 2012**, we will regard it as acceptance and we will proceed to this change.

Thank you in advance for your cooperation and understanding in this matter.

Yours faithfully

K Utsumi/Manager

Business Development Support Sec. II Planning & Market Promotion Dept. Murata Manufacturing Co., Ltd.

K. Uteumi

Appendix1



MURATA PART NO
BNP002-02
BNP002-03
BNP003-03
BNX002-01
BNX002-01
BNX003-01
BNX005-01
BNX012-01
BNX012-01
BNX012H01
BNX012H01
BNX016-01
BNX016-01
BNX022-01B
BNX022-01K
BNX022-01L
BNX102-01
DF40NC21H332XQ00
DF40NC81H332XQ00
DF40NC81H332XQ00
DF40NY81H332XQ00
DF40NY81H332XQ00
DF41NY81H332XQ00
NFA31GD4701014B
NFA31GD4701014D
NFA31GD4703304B
NFA31GD4703304D
NFA31GD4704704B
NFA31GD4704704D
NFA31GD4706R84B
NFA31GD4706R84D
NFE31PT222Z1E9B
NFE31PT222Z1E9K
NFE31PT222Z1E9L
NFE31PT222Z1E9L
NFE31PT222Z1E9L
NFE31PT222Z1E9L
NFE61PT472C1H9B
NFE61PT472C1H9L