

11 April 2011

Dear Customer

We have been informed by the manufacturer OKO that due to improvements in materials and manufacturing process there will be a change to the current rating of the contacts on the following relays, the current rating of the contacts will increase from 8 Amps to 10 Amps, no other specifications are changed.

<b>K5A05</b>	<b>K5A12</b>	<b>K5A24</b>
<b>K5A06</b>	<b>K5A18</b>	<b>K5A48</b>

The relays form & fit are not affected by this change whilst the function has been improved.

The UL approval for these relays been updated to reflect the improved contact ratings and the UL file number remains the same so there is no action required from your side.

The change will take effect from March 2011 on deliveries from OKO to our Distribution centre, Anglia operates a strict FIFO system in our facility therefore it may take some time for this change to filter through to customer deliveries of the above part numbers.

Please ensure this information is circulated to the relevant persons within your organisation to prevent any issues in the supply chain of the above products.

Yours Sincerely

Anglia