

## Product-Change Notification

Products affected: MMS 228, MMS 228 B, MMS 228 BT, MMS 228 T

MMS 238, MMS 238 B, MMS 238 BT, MMS 238 T

Effective date: after current stock is sold out

### Details:


In order to improve the delivery performance of these switches the material of the contact plate was changed to a better available material.

Up to now: copper alloy

From now on: stainless steel.

Technical data, dimensions and all other content of data-sheets are not affected by this change.

knitter-switch, July 2014



Oliver Kluj  
Technical Director