

12 May 2010

Dear Customer

We have been informed by the manufacturer OKO there will be a change to the ink colour used on the following Relays, the colour will change from yellow to white.

<b>K1BE03</b>	<b>K1BE03H</b>	<b>K1C03</b>	<b>K1C03H</b>	<b>47W/5</b>	<b>47W/5H</b>
<b>K1BE05</b>	<b>K1BE05H</b>	<b>K1C05</b>	<b>K1C05H</b>	<b>47W/9</b>	<b>47W/9H</b>
<b>K1BE06</b>	<b>K1BE06H</b>	<b>K1C06</b>	<b>K1C06H</b>	<b>47W/6</b>	<b>47W/6H</b>
<b>K1BE09</b>	<b>K1BE09H</b>	<b>K1C09</b>	<b>K1C09H</b>	<b>47W/7</b>	<b>47W/7H</b>
<b>K1BE12</b>	<b>K1BE12H</b>	<b>K1C12</b>	<b>K1C12H</b>	<b>47W/8</b>	<b>47W/8H</b>
<b>K1BE24</b>	<b>K1BE24H</b>	<b>K1C24</b>	<b>K1C24H</b>		

This change is being made to improve efficiency in the automatic printing step of the manufacturing process. Form, fit, function and safety approvals of the Relays will not be affected by this change. From 1.6.10 this change will take effect on deliveries from OKO to Anglia. Anglia operates a strict FIFO system in our warehouse facility therefore it may take some time for this change to filter through to customer deliveries of the above part numbers.

Please ensure this information is circulated to the relevant persons within your organisation to prevent any issues in the supply chain of the above products.

Yours Sincerely

Anglia