

ID No. 00986	Product/Process Change Notification		Date 20.03.2023	
Product		Ordering Code		
MV31-W USB		L30960N6910A100		
MV31-W PCle		L30960N6920A100		
Ordering Code changes:		⊠ No		
Product		New Ordering Code		
Reason of Change:				
☐ Technical requirement ☐ Customer requirement ☐ Quality improvement		☐ Change of production proces☐ Location of production move ☐ Other: Label change	•	
corres Detail The o		ional Approvals for MV31 product were obtained: KC. The sponding Sign and ID was added to the laser marking of the product. Is are documented in the HID. ordering codes remain the same, no change of firmware or hardware. urther questions feel free to contact your local FAE team.		
Schedule details:				
Availability of SW for evaluation:	NA			
Availability of modules Telit Cinterion wareho		CW18/2022		
Timing note:	contra Telit (If Telit Cinterion Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, Telit Cinterion Deutschland GmbH assumes that the customer agrees to the change.		
Quality assurance		The new version fulfils all internal test requirements according to our		

Attachments:



X Mula Silber

Signed by: Telit.com

Product Program Manager Head of

X i.A. Clemens Schultz

Head of Quality Management IoT Signed by: 01790025383