

19th Jun. 2023

To: Valued Customer

From: Littelfuse Product Management

Subject: Marking change from UR to cURus for specific Cartridge fuses

With regards to the above reference, Littelfuse would like to inform you that the UR marking on

fuse caps and label would be changed from **SU** to **SU** for specific Cartridge fuses.

Please refer to the below example for the details for this change.

	Before	After
Label	CUP MART NOT BOB SSEGG & SMXKS1P ALL DO NOT THE REAL FACE AND CONTROL C	(19) PART NO: 083506.3MXK31P From 2007 for 2000 (1) LOT NO: 1510019-007 (1) LOT NO: 1500000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 1500000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 1500000 (1) LOT NO: 150000 (1) LOT NO: 1500000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 1500000 (1) LOT NO: 1500000 (1) LOT NO: 150000 (1) LOT NO: 1500000 (1) LOT NO: 150000 (1) LOT NO: 150000 (1) LOT NO: 150000000 (1) LOT NO: 15000000000 (1) LOT NO: 150000000000 (1) LOT NO: 150000000000 (1) LOT NO: 15000000000000000000000000000000000000
Fuse Marking on caps		

For all the affected part numbers, the fuses were actually certified to cURus many years ago. As such, this change is to make the marking on the fuse caps and label consistent with what the fuses were certified to.

There are no changes to the existing certificates, no changes in the form, fit and function of the fuses. There is no change to the part number.

We would do the running change for shipments from Jul.15th, 2023 onwards

Part numbers affected are shown on the Excel sheet as per attached.

Please let us know should you have further queries.

Best Regards;

Style Liu Global Product Manager SLiu@Littelfuse.com Tel - +86 512 67613189-2251