

RECALL - Product Discontinuation Notice

Please be informed that Neutrik will be RECALL the Product Discontinuing Notes from certain products.

PDN-RECALL No.:	003
PDN-RECALL Date:	30.01.2026

Affected Products

Neutrik part number	PDN-No	PDN Date	Reason
NC5FAH	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAH-D	003	02.07.2025	The new series differs too much to replace the old one.
NC5MAV	003	02.07.2025	The new series differs too much to replace the old one.
NC5FBV-SW	003	02.07.2025	The new series differs too much to replace the old one.
NC5MAH	003	02.07.2025	The new series differs too much to replace the old one.
NC5MBV	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAV	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAV-D	003	02.07.2025	The new series differs too much to replace the old one.
NC5FBV-D	003	02.07.2025	The new series differs too much to replace the old one.
NC5FBV	003	02.07.2025	The new series differs too much to replace the old one.
NC5MBH	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAV-SW	003	02.07.2025	The new series differs too much to replace the old one.
NC5MBH-B	003	02.07.2025	The new series differs too much to replace the old one.

NC5FBV-B	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAV-SW-D	003	02.07.2025	The new series differs too much to replace the old one.
NC5MBV-B	003	02.07.2025	The new series differs too much to replace the old one.
NC5MAV-SW	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAH-LR-DAE	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAH-0	003	02.07.2025	The new series differs too much to replace the old one.
NC5MAH-LR	003	02.07.2025	The new series differs too much to replace the old one.
NC5FAH-DA	003	02.07.2025	The new series differs too much to replace the old one.
NC5MBV-SW	003	02.07.2025	The new series differs too much to replace the old one.