

March 7, 2024

Product Change Notice #032402

Type of Change: End of Life Material Change
 Facility Change Process Change
 Design Change Other

Part Series Affected: LVK25 (Full list of affected parts numbers included on next page)

Description of Change: There were several dimensional changes made to the LVK25 part numbers in the Ohmite catalog. The new dimensions for this series of parts can be found here in the [current datasheet](#).

Reason for Change: A manufacturing error was causing uneven electrode dimensions in the LVK25 series. To prevent this problem from occurring, a modification was made to the electrode pattern of the LVK25's. This has solved the uneven electrodes, but it means the dimensions of the LVK25 needed to be adjusted.

Expected Influence on Quality/Reliability/Performance: There is no expected change in quality, reliability, or performance. The only change was in the physical dimensions of the LVK25.

Effective Date: 3/7/2024

Date Last Time Buy: N/A

Date of Last Time Shipment: N/A

Recommended Replacement: N/A

For further technical questions related to this PCN, please contact dchakraborty@ohmite.com.

Best Regards,

Joe Misulonas
Marketing Manager
jmisulonas@ohmite.com

Information, data and drawings embodied in this correspondence are strictly confidential and are supplied on the understanding that they will be held confidentially and not disclosed to third parties without the prior written consent of Ohmite Manufacturing Company, Inc.

Part Numbers Affected

LVK25R001DER

LVK25R001FER

LVK25R002DER

LVK25R002FER

LVK25R003DER

LVK25R003FER

LVK25R005CER

LVK25R005DER

LVK25R005FER

LVK25R010CER

LVK25R010DER

LVK25R010FER