



PCN-0842-25-0006	Product Change Notification New SW Introduction	Date 05.08.2025
Products: WE310F5-P / WE310F5-I		
Ordering Code changes: ☒ Yes ☐ No		

Product Name	Current Ordering Code	FW Version	Status	Replacement Ordering Code TELIT STYLE commands	Replacement Ordering Code TELIT LEGACY commands
WE310F5-P	WE310F5P396R001000 WE310F5P396T001000	39.00.006	NRND	WE310F5P20CT001000 WE310F5P20CR001000	WE310F5P30CR005000
	WE310F5P397R001000 WE310F5P397T001000	39.00.007	NRND	WE310F5P20CT001000 WE310F5P20CR001000	WE310F5P30CR005000
	WE310F5P398R001000 WE310F5P398T001000	39.00.008	NRND	WE310F5P20CT001000 WE310F5P20CR001000	WE310F5P30CR005000
	WE310F5P20BR001000 WE310F5P20BT001000	39.02.011	NRND	WE310F5P20CT001000 WE310F5P20CR001000	N/A
WE310F5-I	WE310F5I396R001000 WE310F5I396T001000	39.00.006	NRND	WE310F5I20CT001000 WE310F5I20CR001000	WE310F5I30CR005000
	WE310F5P397R001000 WE310F5P397T001000	39.00.007	NRND	WE310F5I20CT001000 WE310F5I20CR001000	WE310F5I30CR005000
	WE310F5P398R001000 WE310F5P398T001000	39.00.008	NRND	WE310F5I20CT001000 WE310F5I20CR001000	WE310F5I30CR005000

Reason of Change:

- ☐ Technical requirement
- ☐ Customer requirement
- ☒ Quality improvement
- ☐ Change of production process/logistical changes
- ☐ Location of production
- ☒ Other: New Software introduction

Description of change:	New firmware release 39.0x.012 for the WE310F5-I/P Wi-Fi 4 Module. We, Telit Cinterion, would like to inform you about the availability of new ordering codes with firmware release 39.02.012: Telit Style commands 39.03.012: Telit Legacy commands for WE310F5 Series. The new ordering codes listed in the table above comply with the requirements of EU RED Delegated Act on Cybersecurity (Commission Delegated Regulation (EU) 2022/30), commonly known as "RED Cybersecurity requirements".
------------------------	--



	The Software release note documents and the full software package are available in Telit Cinterion website into Download Zone or via the Technical Support team. Alongside with the introduction of this new firmware, modules with previous firmware version have to be considered as Not Recommended for New Designs (NRND).
Quality assurance measurements:	These new SW 39.0x.012 fulfil all internal test requirements according to our Quality Management process and philosophy.

If you have any question about the present communication, please contact Telit Cinterion Technical Support or your Regional Sales Representative.

Signed by:

Eric Lagorce

000FDB0E8347484...

Eric Lagorce

Product Management

Signed by:



483139AD3AE9485...

Joerg Erdmann

Head of IoT Quality