

ID No. 916	Product/Process Change Notification	Date 2022-8-29
Product	Ordering Code	
PLS63-EP Rel.1.2	L30960-N6560-A120	
Ordering Code changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Product	New Ordering Code	

Reason of Change:

- | | |
|---|--|
| <input checked="" type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	<p>Dear customer,</p> <p>Thales will introduce a new firmware for the PLS63-EP Rel.1.2 that implements stability and functional improvements; for details please refer to the corresponding Release Note (RN).</p> <p>The new firmware is GCF and Telstra approved.</p> <p>Part number will not be changed.</p> <p>The old software application string is:</p> <p style="text-align: center;">Rev 01.201 ARN 01.000.00 SVN 11</p> <p>The new software application string is:</p> <p style="text-align: center;">Rev 01.202 ARN 01.000.04 SVN 12</p>
Schedule details:	CW/YEAR
Availability of SW for evaluation:	CW33/2022
Availability of modules ex THALES DIS AIS Deutschland warehouse:	CW45/2022
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

Quality assurance measurements:

The new version fulfils all internal test requirements according to our Quality Management process and philosophy.

Attachments:

2022/9/2

06.09.2022

X WANG JIANFENG

Product Program Manager
Signed by: WANG Jianfeng

X 

Head of Quality Management IoT
Signed by: ERDMANN Joerg