THALES

ID No. 921 Produc		ıct/Process	Change Notification	Date 10.10.2022	
Product		Orderin	Ordering Code		
PLS62-W Rel.1		L30960N	N4600A100		
Ordering Code changes:		Yes	⊠No		
Product			New Ordering Code		
Reason of Change:			☐ Change of production proces	se/logistical changes	
☐ Customer requirement			Location of production move	•	
☐ Quality improvement			Other:		
Description of change:			about introduction of 2 nd source me -W Rel.1 module.	emory for our	
			roduct vendor announced PCN fro I provide new MID (Manufacturer I		
		change the origin customer's modu	product's datasheet, this 2 nd memoral al memory functions and performa le design will not be affected. Thal memory source successfully.	ances at all, and the	
	r	nodules will have	with this 2 nd memory source, the sea minor adaption to identify the nuce the new FW to the above prod	ew memory MID.	
	-	The new software	application string is:		
		SVN 0	5 Rev 02.013 ARN 01.000.15		
	-	The new FW has	been certified with GCF/PTCRB/A	T&T approvals.	
	1	No regulatory cer	tification update required.		
			r questions, our FAE team who off , should be contacted.	fers comprehensive	
Schedule details: CW/Y		CW/YEAR			
Availability of SW for evaluation:		CW41/2022			
Availability of modules ex THALES DIS AIS Deutschland warehouse:		CW48/2022			

THALES

If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks,
THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

Attachments:

10/13/2022 13.10.2022

X July

Product Program Manager Signed by: SUN Xiao-Lin X i. Voi duam

Head of Quality Management IoT Signed by: ERDMANN Joerg