

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	005	5116	0000001135	GSF1.0205.04	Connector	GSF1	
02	005	5116	0000001135	GSF1.0402.01	Connector	GSF1	
02	005	5116	0000001135	GSF1.2002.34	Connector	GSF1	
02	005	5116	0000001135	GSF1.3402.01	Connector	GSF1	
02	005	5116	0000001135	GSF1.4401.04	Connector	GSF1	
02	005	5116	0000001135	GSF1.4402.01	Connector	GSF1	
02	005	5116	0000001135	GSF1.5402.01	Connector	GSF1	
02	005	5116	0000001135	GSF1.9001	Connector	GSF1	
02	005	5116	0000001135	GSF1.9005	Connector	GSF1	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

Packaging

3 Detailed description of change



old Blister

Material: PS Polystyrene black ; ESD conform



new Blister

Material: PS Polystyrene white : none ESD conform
Connector in new orientation

4 Reason of change

Packaging harmonisation

5 Released date

Released of production

01/13

6 Impact of change and recommended action

Form: n/a
Fit: n/a
Function: n/a
Production Site: Connector in new orientation
Product Label: n/a

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Notification of change	23788	

GSF1					0118.2119	
creation date	created by	release date	released by	notification no.	revision	page
2012-08-16	hol			23788	_00	1 of 1