

1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PGU Type				
02 007 003 0000002363	See list below	Appliance inlet	1681	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
6173.0001	6173.0010	6173.0015	6173.0020	6173.0025
6173.0002	6173.0011	6173.0016	6173.0021	6173.0026
6173.0003	6173.0012	6173.0017	6173.0022	6173.0027
6173.0004	6173.0013	6173.0018	6173.0023	6173.0028
6173.0009	6173.0014	6173.0019	6173.0024	


2 Type of change

Modification of rating mark




3 Detailed description of change

Change of rated current acc. to UL 60320

Old marking



New marking



4 Reason of change

Rated current adjusted to UL 60320

1681 Appliance Inlet					0118.2196	
creation date	created by	release date	released by	notification no.	revision	page
2014-01-06	helbljo	2014-02-11	hotzar	25633		1 of 2

5 Release date

The change will be rolled-out individually by all part numbers affected starting ww 08/2014 and last approx. 9 months.

6 Impact of change and recommended action

Form: New current rating according to UL 60320
Fit: N/A
Function: N/A
Production Site: N/A
Product Label: N/A

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet 1681		

1681 Appliance Inlet					0118.2196	
creation date	created by	release date	released by	notification no.	revision	page
2014-01-06	helbljo	2014-02-11	hotzar	25633	—	2 of 2