

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	007	003	0000002298	See list below	Connectors	4798	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)


List of part numbers affected				
4798.9000	4798.9000.15	4798.9000.16	4798.9000.21	4798.9100
4798.9100.15	4798.9100.16	4798.9100.21	4798.9200	4798.9200.15
4798.9200.16	4798.9200.21	4798.9201.16	4798.9800	4798.9900

2 Type of change

Each product marked with individual part number.

3 Detailed description of change

Place of marking on product.



4 Reason of change

Part number on product for identification and administrative reasons.

5 Release date

The change will be rolled-out individually by all part numbers affected starting ww 01/2014 and last approx. 6 months.

6 Impact of change and recommended action

Form: N/A
Fit: N/A
Function: N/A
Production Site: N/A
Product Label: Part number on product

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet 4798		

4798					0118.2191	
creation date	created by	release date	released by	notification no.	revision	page
2013-10-16	hermanur	2013-11-26	hermanur	25254	-	1 of 1