

## Product Change Notice

Issue Date: 19<sup>th</sup> March 2012

**Type of Change(s):**

Country of origin (COO) device marking simplification for Seven Segment Displays (S4) and Annunciators.

**Parts Affected:**

Seven Segment Displays (S4) part number list:

5082-7610	HDSP-5503-GG000	HDSP-7807	HDSP-F211-DE000	HDSP-K213-GH000
5082-7610-CD000	HDSP-5503-GH000	HDSP-7808	HDSP-F213	HDSP-K511
5082-7611	HDSP-5507	HDSP-8601	HDSP-F213-DE000	HDSP-K511-GH000
5082-7611-DE000	HDSP-5507-GG000	HDSP-8601-EF000	HDSP-F301	HDSP-K513
5082-7613	HDSP-5507-GH000	HDSP-8603	HDSP-F301-DE000	HDSP-K513-GH000
5082-7613-CD000	HDSP-5508	HDSP-8603-EF000	HDSP-F303	HDSP-N101
5082-7620	HDSP-5508-GH000	HDSP-A101	HDSP-F303-DE000	HDSP-N103
5082-7621	HDSP-5521	HDSP-A101-FG000	HDSP-F303-DE016	HDSP-N103-CD000
5082-7623	HDSP-5521-GG000	HDSP-A103	HDSP-F401	HDSP-N105
5082-7650	HDSP-5521-GH000	HDSP-A103-FG000	HDSP-F403	HDSP-N150
5082-7651	HDSP-5523	HDSP-A107	HDSP-F413	HDSP-N151
5082-7651-DE000	HDSP-5523-GH000	HDSP-A107-FG000	HDSP-F501	HDSP-N153
5082-7653	HDSP-5551	HDSP-A108	HDSP-F501-JK000	HDSP-U101
5082-7653-DE000	HDSP-5553	HDSP-A111	HDSP-F503	HDSP-U103
5082-7656	HDSP-5553-BC000	HDSP-A113	HDSP-F503-JK000	HDSP-U111
5082-7661	HDSP-5557	HDSP-A125	HDSP-F503-JK016	HDSP-U111-EG000
5082-7663	HDSP-5558	HDSP-A151	HDSP-F511	HDSP-U113
5082-7666	HDSP-5601	HDSP-A153	HDSP-F511-IJ000	HDSP-U113-FG000
HDSP-315E	HDSP-5601-GH000	HDSP-A153-NO000	HDSP-F511-IJC00	HDSP-U201
HDSP-315G	HDSP-5603	HDSP-A211	HDSP-F513	HDSP-U203
HDSP-315H	HDSP-5603-GH000	HDSP-A213	HDSP-F513-IJ000	HDSP-U203-CD000
HDSP-315L	HDSP-5607	HDSP-A213-CD000	HDSP-G101	HDSP-U211
HDSP-315Y	HDSP-5607-GH000	HDSP-A401	HDSP-G103	HDSP-U211-CD000
HDSP-316E	HDSP-5608	HDSP-A403	HDSP-G111	HDSP-U213
HDSP-316G	HDSP-5621	HDSP-A413	HDSP-G113	HDSP-U213-CD000
HDSP-316H	HDSP-5621-GH000	HDSP-A511	HDSP-G201	HDSP-U301
HDSP-316L	HDSP-5621-GH400	HDSP-A511-JK000	HDSP-G201-EF000	HDSP-U303
HDSP-316Y	HDSP-5623	HDSP-A513	HDSP-G203	HDSP-U311
HDSP-316Y-KMP00	HDSP-5623-GH000	HDSP-A801	HDSP-G211	HDSP-U313
HDSP-3351	HDSP-5701	HDSP-A803	HDSP-G213	HDSP-U401
HDSP-3353	HDSP-5701-FG000	HDSP-A807	HDSP-G501	HDSP-U403
HDSP-3356	HDSP-5703	HDSP-A901	HDSP-G503	HDSP-U411
HDSP-3600	HDSP-5703-FG000	HDSP-A903	HDSP-G511	HDSP-U413
HDSP-3601	HDSP-5721	HDSP-A903-GHC00	HDSP-G513	HDSP-U413-LN000
HDSP-3603	HDSP-5721-FG000	HDSP-A907	HDSP-H101	HDSP-U501
HDSP-3900	HDSP-5723	HDSP-A908	HDSP-H101-CD000	HDSP-U501-J0C00
HDSP-3901	HDSP-5811	HDSP-E100	HDSP-H101-DE000	HDSP-U503
HDSP-3901-EF000	HDSP-5813	HDSP-E101	HDSP-H103	HDSP-U503-KL000



HDSP-3903	HDSP-7401	HDSP-E101-EF000	HDSP-H103-DE000	HDSP-U511
HDSP-3903-EF000	HDSP-7401-DE000	HDSP-E103	HDSP-H107	HDSP-U511-KL000
HDSP-3905	HDSP-7403	HDSP-E150	HDSP-H108	HDSP-U513
HDSP-4201	HDSP-7403-DE000	HDSP-E151	HDSP-H111	HDSP-U513-KL000
HDSP-4203	HDSP-7501	HDSP-E153	HDSP-H111-DE000	QDSC-A000
HDSP-4600	HDSP-7501-CD000	HDSP-F101	HDSP-H113	QDSP-7590
HDSP-4601	HDSP-7502	HDSP-F101-EF000	HDSP-H151	QDSP-F140
HDSP-4603	HDSP-7502-CD000	HDSP-F103	HDSP-H153	QDSP-K580
HDSP-4603-IJ000	HDSP-7503	HDSP-F103-EF000	HDSP-H157	QDSP-S023
HDSP-4606	HDSP-7503-CD000	HDSP-F107	HDSP-H158	QDSP-S062
HDSP-4606-IJ000	HDSP-7503-DD000	HDSP-F108	HDSP-H211	QDSP-U233
HDSP-515E	HDSP-7504	HDSP-F111	HDSP-H211-GH000	QDSP-U236
HDSP-515G	HDSP-7507	HDSP-F111-EF000	HDSP-H213	QDSP-U237
HDSP-515H	HDSP-7508	HDSP-F113	HDSP-H213-GH000	QDSP-U239
HDSP-515H-GH000	HDSP-7511	HDSP-F151	HDSP-H413	5082-7650-DD000
HDSP-515L	HDSP-7511-CD000	HDSP-F151-MN000	HDSP-H413-EF000	5082-7651-DD000
HDSP-515L-FG000	HDSP-7513	HDSP-F153	HDSP-H413-FG000	QDSP-A586
HDSP-515Y	HDSP-7513-CD000	HDSP-F153-NO000	HDSP-H511	QDSP-7488
HDSP-516E	HDSP-7517	HDSP-F157	HDSP-H511-GH000	
HDSP-516G	HDSP-7801	HDSP-F158	HDSP-H513	
HDSP-516H	HDSP-7801-JK000	HDSP-F161	HDSP-H513-GH000	
HDSP-516L	HDSP-7801-KK000	HDSP-F201	HDSP-K111	
HDSP-516Y	HDSP-7802	HDSP-F201-DE000	HDSP-K113	
HDSP-516Y-KMP00	HDSP-7802-JK000	HDSP-F203	HDSP-K121	
HDSP-5501	HDSP-7803	HDSP-F203-DE000	HDSP-K123	
HDSP-5501-GG000	HDSP-7803-JK000	HDSP-F207	HDSP-K211	
HDSP-5501-GH000	HDSP-7803-JKC00	HDSP-F208	HDSP-K211-GH000	
HDSP-5503	HDSP-7804	HDSP-F211	HDSP-K213	

Annunciator part number list:

HDSP-4830	HLCP-D100	HLMP-2450-EF000	HLMP-2685-EF000	HLMP-2835
HDSP-4830-GH000	HLCP-E100	HLMP-2500	HLMP-2700	HLMP-2855
HDSP-4830-HH000	HLCP-E100-BC000	HLMP-2500-FG000	HLMP-2700-EF000	HLMP-2855-FG000
HDSP-4832	HLCP-F100	HLMP-2516	HLMP-2720	HLMP-2870
HDSP-4836	HLCP-G100	HLMP-2550	HLMP-2720-EF000	HLMP-2870-FG000
HDSP-4840	HLCP-H100	HLMP-2550-FG000	HLMP-2735	HLMP-2885
HDSP-4840-FG000	HLCP-H100-BC000	HLMP-2598	HLMP-2755	HLMP-2885-FG000
HDSP-4840-FGB00	HLCP-J100	HLMP-2599	HLMP-2755-EF000	HLMP-2950
HDSP-4850	HLMP-2300	HLMP-2600	HLMP-2755-EFB00	HLMP-2965
HDSP-4850-HI000	HLMP-2300-EF000	HLMP-2620	HLMP-2770	QDSP-4985
HDSP-4850-HIC00	HLMP-2350	HLMP-2620-EF000	HLMP-2785	QLCP-B247
HLCP-A100	HLMP-2350-EF000	HLMP-2635	HLMP-2785-EF000	QLCP-M096
HLCP-A100-BC000	HLMP-2366	HLMP-2655	HLMP-2785-EFB00	QLMP-2976
HLCP-B100	HLMP-2400	HLMP-2655-EF000	HLMP-2800	
HLCP-B100-BC000	HLMP-2400-EF000	HLMP-2670	HLMP-2820	
HLCP-C100	HLMP-2450	HLMP-2685	HLMP-2820-FG000	



**Description and Extent of Changes:**


Country of origin device marking simplification from “THAILAND” to “TH”.

**Reasons for Change:**

To improve marking performance and efficiency.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

Changes are confined to device marking only. There is no change on the fit, form, function, quality or reliability of the devices.

Current COO marking	New COO marking
	

**Effective Date of Change:**

Avago Technologies will begin to ship these parts starting 19 March 2012. There may be mixed shipments between current and new COO marking parts until inventory is fully depleted.

**Qualification Data**

Not applicable as there is no change in product fit, form and function.

Please contact your Avago field sales engineer for further details or support requirements.

Thank you for your continuous attention to these changes.

---

These changes have been reviewed and approved by Avago Technologies engineers and managers per Avago Technologies procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/> ) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.