

Product change notification (PCN)

Title / short description	FL SWITCH 4000E update due to component shortage
Affected article category	Industrial communication technology
Change category	Production process
Change number	CDN210051-01
Reason for PCN/PDN Revision	

Purpose/objective of the change

Component availability and obsolescence

Detailed description of the change

In order to maintain shipments with rapid component availability changes, we have changed to a more readily-available component. This requires the use of new FL SWITCH 4800T-PXB power modules.

Identifying characteristics

All modified items can be identified by the incremented production batch.

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2021-10-29	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☒ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- CDN210051_current product state.jpg
- CDN210051_future product state.jpg
- Material_list.csv
- PCN-CDN210051-01 Aktualisierung bei FL SWITCH 4000E aufgrund einer Bauteilknappheit_DE
- PCN-CDN210051-01 FL SWITCH 4000E update due to component shortage_EN

Material list

Item	Article Type	Hardware / Firmware old	new	Item	Substitute item Type
2891072	FL SWITCH 4824E-4GC	05	06		
2891079	FL SWITCH 4808E-16FX-4GC	05	06		