

6th June 2014


PCN 140521

Dear Customer,


Part numbers affected: THD15FPR
THD15FPRC

We have been advised by TAICOM that new tooling has been implemented for the above part number, the new tooling changes the physical appearance, but does not affect the fit or function of the part.

Old version



New version



Parts manufactured using the new tooling will commence shipment to Anglia from the 1st June 2014 and as Anglia operates a strict FIFO system in our Distribution Centre it may take some time for this change to filter through to customer deliveries of the above part number.

Please make the relevant person(s) in your organisation aware of this change.

Yours Sincerely
Anglia