

Engineering Change Notice ECR00126

| | |
|-------------------------------|-----------------------|
| Part number/s: | M10478-A3 / M10578-A3 |
| Description of change: | Firmware update |
| Change Effective by: | October 2017 |

The M10478-A3 and M10578-A3 GNSS modules have an implemented engineering change due to chip supplier upgrade to FW. This change of release has no effect on any hardware design, and the update is fully back compatible with the previous version. No hardware changes have been made to the module.

| | |
|--------------------------------|---|
| Firmware Revision: | AN-10-0018-A |
| Description of changes: | <ul style="list-style-type: none"> - MT3333 FW update to include GALILEO constellation function. This allows simultaneous running of GPS+GLONASS+GALILEO - FIX Indicator pin now functional for logic high when 3D fix is acquired. |
| Change Effective by: | October 2017 |

Part identification

Modules with the updated FW version are identified on the packaging label with the new FW code AN-10-0018-A shown below:

