

Product Change Notification





MK-009921-SL

Issue Date : 01 April 2016

Dear Valued Customer,

Due to our ongoing product improvement initiatives, it is now proposed to up issue DX1090 and DX1091's in line with this. The changes include the change of the O-ring 12459 to 15163.

O-ring 12459	O-ring 15163
 <p>Technical drawing of O-ring 12459. The top view shows an outer diameter of $\phi 7.112$. The cross-section view shows a diameter of $\phi 1.016$.</p>	 <p>Technical drawing of O-ring 15163. The top view shows an outer diameter of $\phi 6.50$. The cross-section view shows a diameter of $\phi 1.50$.</p>

Affects part numbers: DX1090 & DX1091

If you have any questions about this change, please do not hesitate to contact your local sales representative or authorised distributors.