

## Product Change Notice

PCN#:EE-PCN20002


April 1, 2020

### CLASSIFICATION OF CHANGE:

Shrink Sleeve Marking

### DESCRIPTION OF CHANGE:


Change negative lead indicator on all supercapacitor packs. New stripe will be visible from the side and from the ends at all angles.



Existing



Stripe aligned with negative lead



New

### REASON FOR CHANGE:

Improve customer auto placement machines optical read rates for proper orientation.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

None

### PARTS FAMILIES AFFECTED:

PB family  
PHB family  
PHV family

### TIME SCHEDULE:

Start Shipment  
Date: June 15th, 2020

### SAMPLE AVAILABILITY:

Not applicable

### QUALIFICATION DATA:

Not applicable

### ISSUED BY:

Product Manager: Jason Lee

### CONTACT INFORMATION:

For questions or comments, please contact <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html>