

ID No. 00616	Product/Process Change Notification Date 6 December 2		Date 6 December 2018
Product		Ordering Code	
ELS61-E Rel. 2		L30960N4450A200	
Ordering No. changes:		🗌 Yes 🛛 No	
New Ordering Code	:		

## **Reason of Change:**

Technical requirement	Change of production process/logistical changes
Customer requirement	Location of production moved
🛛 Quality improvement	Other:

Description of change:	Gemalto M2M GmbH is going to introduce a maintenance release to improve the overall system performance of the product.	
	Following modifications have been implemented:	
	<ul> <li>Improve the HPLMN scan mechanism, then UE can camp to the correct and higher priority PLMN much quicker</li> </ul>	
	- Update a parameter to avoid damage caused by unintended current in rare stress test case	
	- improve consecutive call performance	
	FW revision remains the same.	
	In case of questions about support of previous versions please contact local sales organization.	
Scheduled date of introduction (cw/year):	CW 4/2019	
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks. Gemalto M2M GmbH assumes that the customer agrees to the change.	

Quality assurance measurements:The new version fulfills all internal test requirements according to our Quality Management process and philosophy.	-	
---	---	--

17.12.2018

X Ivonne Krüger

Ivonne Krüger Product Lifcycle Manager Signed by: Ivonne Krueger 10015065

i. Voi Aucun

Jörg Erdmann Vice President Quality Management Signed by: Joerg Erdmann 10015214

## Attachments:

19.12.2018