



ID No. 761	Product/Process Change Notification		Date 23.03.2020
Product		Ordering Code	
mPLS62-W		L30960-N3230-A300	
Ordering Code changes:		🗌 Yes 🛛 No	
Product		New Ordering Code	

Reason of Change:

- Technical requirement
- Customer requirement
- \boxtimes Quality improvement

Change of production process/logistical changes
 Location of production moved

Other:

Description of change:	 Introduction of minor modifications on Java embedded platform based on module PLS62-W (see PCN00757). The implemented change improves the directory path access check of internal flash file system, which can store application-specific data or data needed for customer Java applications, TLS and OTAP functionality. All changes are done on application layer only. For identification of improved firmware a new SVN, RN and ARN will be introduced same as corresponding PTCRB and AT&T approval update for the module. New: SVN 02, RN 02.010, ARN 01.000.05 If there are further questions, our Technical Sales team who offers comprehensive customer support, should be contacted.
Schedule details:	CW/YEAR
Availability of SW for evaluation:	CW18/2020
Availability of modules ex THALES DIS AIS Deutschland warehouse:	CW18/2020
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

Quality assurance	The new version fulfils all internal test requirements according to our
measurements:	Quality Management process and philosophy.

Attachments:





03.04.2020

23.03.2020

Erke fell

Product Lifecycle Manager Signed by: ESTENFELDER Walter

Voi Aucun

Vice President Quality Management Signed by: ERDMANN Joerg