



ID No. 00366	<b>Product/Process Change Notification</b>	Date 22 December 2015
<b>Product</b>	<b>PXS8 Rel.3</b> <b>PXS8 CI Rel.3</b> <b>PXS8 I Rel.3</b>	
<b>Ordering Code</b>	<b>L30960N2600A300</b> <b>L30960N2605A300</b> <b>L30960N2610A300</b>	
	Ordering No. changes: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
	New Ordering Code:	

**Reason of Change:**

- |   |  |
|---|--|
| <input type="checkbox"/> Technical requirement          | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement           | <input type="checkbox"/> Location of production moved                    |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other:  |

<b>Description of change:</b>	<p>This new software improves the stability of the products listed above including:</p> <ul style="list-style-type: none"> <li>- Support of GPS after End 2019 (GPS Rollover after 19,6 years)</li> <li>- Support of additional memory ID (Jeju)</li> <li>- Improvements in the flash driver</li> <li>- Improved robustness for firmware upgrade related to 2<sup>nd</sup> source memory</li> <li>- Overall system stability improved</li> </ul> <p>The new application revision string of is ARN = 01.006.15  GTO strongly recommends migrating to this new SW version.  This application related changes are not approval relevant.</p>													
<b>Scheduled date of introduction (cw/year):</b>	<table border="1"> <thead> <tr> <th></th> <th><u>Provision of SW</u></th> <th><u>Start of first shipments ex warehouse</u></th> </tr> </thead> <tbody> <tr> <td><b>PXS8 Rel. 3</b></td> <td><b>CW03/2016</b></td> <td>not before <b>CW08/2016</b></td> </tr> <tr> <td><b>PXS8 CI</b></td> <td><b>CW03/2016</b></td> <td>not before <b>CW09/2016</b></td> </tr> <tr> <td><b>PXS8 I</b></td> <td><b>CW03/2016</b></td> <td>not before <b>CW10/2016</b></td> </tr> </tbody> </table> <p><b>Please note that a SW downgrade to earlier SW is not supported and could cause damage of the module!</b></p>		<u>Provision of SW</u>	<u>Start of first shipments ex warehouse</u>	<b>PXS8 Rel. 3</b>	<b>CW03/2016</b>	not before <b>CW08/2016</b>	<b>PXS8 CI</b>	<b>CW03/2016</b>	not before <b>CW09/2016</b>	<b>PXS8 I</b>	<b>CW03/2016</b>	not before <b>CW10/2016</b>	
	<u>Provision of SW</u>	<u>Start of first shipments ex warehouse</u>												
<b>PXS8 Rel. 3</b>	<b>CW03/2016</b>	not before <b>CW08/2016</b>												
<b>PXS8 CI</b>	<b>CW03/2016</b>	not before <b>CW09/2016</b>												
<b>PXS8 I</b>	<b>CW03/2016</b>	not before <b>CW10/2016</b>												
<b>Timing note:</b>	<p>If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.</p>													
<b>Quality assurance measurements:</b>	<p>The new version fulfills all internal test requirements according to our Quality Management process and philosophy.</p>													

<b>Product Lifecycle Manager/Name:</b> <b>Signature:</b>	Stefan Ludwig 
<b>Quality Management/Name:</b> <b>Signature:</b>	Clemens Schultz <i>i.A.</i> 

Attachments: