



ID No. 00367	Product/Process Change Notification	Date 02 February 2015
Product	Ordering Code	
PHS8-US Rel.3	L30960N2400A300	
PHS8-US CI Rel.3	L30960N2405A300	
PHS8-USA Rel.3	L30960N2420A300	
PHS8-E Rel.3	L30960N2440A300	
PH8 Rel.3	L30960N1900A300	
PH8 P Rel.3	L30960N1910A300	
PH8 P CI Rel.3	L30960N1915A300	
	Ordering No. changes: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
	New Ordering Code:	

Reason of Change:

- | | |
|---|--|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	<p>This new software improves the stability of the products listed above including:</p> <ul style="list-style-type: none"> - Support of GPS after End 2019 (GPS Rollover after 19,6 years) - Support of additional memory ID (Jeju) - Improvements in the flash driver - Improved robustness for firmware upgrade related to 2nd source memory - Overall system stability improved <p>The application revision string of SW 03.001 is ARN = 01.001.24</p> <p>This application related changes are not approval relevant.</p> <p>Migration to this SW version is mandatory to assure further delivery.</p>														
Scheduled date of introduction (cw/year):	<p>Provision of SW: available</p> <p>Start of first shipments ex warehouse:</p> <table border="0"> <tr> <td>PHS8-US Rel.3</td> <td>not before CW12/2016</td> </tr> <tr> <td>PHS8-US CI Rel.3</td> <td>not before CW12/2016</td> </tr> <tr> <td>PHS8-USA Rel.3</td> <td>not before CW12/2016</td> </tr> <tr> <td>PHS8-E Rel.3</td> <td>not before CW13/2016</td> </tr> <tr> <td>PH8 Rel.3</td> <td>not before CW13/2016</td> </tr> <tr> <td>PH8 P Rel.3</td> <td>not before CW13/2016</td> </tr> <tr> <td>PH8 P CI Rel.3</td> <td>not before CW13/2016</td> </tr> </table> <p>Please note that a SW downgrade to earlier SW than Rel. 03.001 ARN 01.001.24 is not supported and could cause damage of the module!</p>	PHS8-US Rel.3	not before CW12/2016	PHS8-US CI Rel.3	not before CW12/2016	PHS8-USA Rel.3	not before CW12/2016	PHS8-E Rel.3	not before CW13/2016	PH8 Rel.3	not before CW13/2016	PH8 P Rel.3	not before CW13/2016	PH8 P CI Rel.3	not before CW13/2016
PHS8-US Rel.3	not before CW12/2016														
PHS8-US CI Rel.3	not before CW12/2016														
PHS8-USA Rel.3	not before CW12/2016														
PHS8-E Rel.3	not before CW13/2016														
PH8 Rel.3	not before CW13/2016														
PH8 P Rel.3	not before CW13/2016														
PH8 P CI Rel.3	not before CW13/2016														

Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.
Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.
Product Lifecycle Manager/Name: Signature:	Stefan Ludwig 
Quality Management/Name: Signature:	Jörg Erdmann 

Attachments: