


21st August 2015

Dear Customer

We have been informed by manufacturer Calinar there has been a change to the surface finish used on part number SFV019WB. The finish has changed from bright tin plating (right image) to matt tin plating (left image).



The plating finish change has been implemented to further improve the consistency and reliability of soldering during the assembly process. Form, fit and function are not affected by this change.

This change is being implemented with immediate effect on deliveries from Calinar to Anglia. Anglia operates a strict FIFO system in our warehouse facility therefore it may take some time for this change to filter through to customer deliveries of the above part number.

Please ensure this information is circulated to the relevant persons within your organisation to prevent any issues in the supply chain of the above products.

Yours Sincerely,
Anglia