	HF46F Product packaging change	Versions: 2
	PMI_20200706	Page 1 / of 2

Subject of Change

Notice on packaging changes for HF46F Family

Affected Products



Complete HF46F Family

Reason for Change


Improve protection for relays - blister and tube packaging.

Change detail:


Blister changes:

Before change	After change
	

The size of the inner slots of the blister to accommodate the relay is too large and it is easy to shake the product. The relay will be now better protected in the blister, because the size of the inner groove will be reduced and the structure will be changed. The outer dimensions of the modified blister will be unchanged.

	HF46F Product packaging change	Versions: 2
	PMI_20200706	Page 2 / of 2

Tube change:



Hongfa used 2 types of tubes, the plan is it to use in future only 1 tube for the packing for HF46F. To unify tube packing and reduce tube packing type, Hongfa plans to remain 2-type tube packing type. The change has an influence to the inner structure, the length and outline dimension will not be changed

Both changes have no influence to the size and qty of the packaging.

Time Schedule for Change:

September 2020 – Hongfa production start