

Date : 2016. 08.08

Dear Sirs & Madams,

Please be informed that the following technical changes will be implemented to the following product you are currently purchasing.

### 1. Product

Part Name	TX18D35VM0APA, TX18D37VM0APA, TX18D44VM2BPA, TX18D46VM2BPA, TX18D203VM2BPA, TX18D205VM0BPA
-----------	---

### 2. Contents of Change

Touch Panel Vendor change : JTouch Corporation → Transtouch Technology Inc.

### 3. Impact on Product Specification

Touch panel electrical characteristics:

TX18D35VM0APA, TX18D37VM0APA

	Item	Current	New
Resistance Between Terminal	X1-X2	400~1200Ω	300~1400Ω
	Y1-Y2	160~660Ω	100~900Ω

TX18D44VM2BPA, TX18D46VM2BPA, TX18D203VM2BPA

	Item	Current	New
Resistance Between Terminal	X1-X2	400~1200Ω	300~1400Ω
	Y1-Y2	190~660Ω	100~900Ω

TX18D205VM0BPA

	Item	Current	New
Resistance Between Terminal	Y1-Y2	100~700Ω	100~900Ω
	-	80% min	77% min

Further details will be specified in the CAS.

### 4. Reasons of Change

To use equivalent material for lead time improvement and long term supply.

### 5. Schedule

Running change will be implemented from Oct.2016 onward.

Please let us know if this change causes any problem to you.

Thank you for your understanding.

Proposed by :

S. Z Lin

Shi-Zhe Lin / Section Manager

Element Design Section

Design Dept.

Product Business Unit 1