



## Notice About Adding Production-site of K7 DC Type Relay









**Dear Customer,**

Anglia have been informed by the supplier OKO that they have implemented some adjustment on production of the listed K7DC (direct current) type relay. A new production-site has been added in Xiamen in which the listed DC type relays will be produced by automatic production line. Please see below for the changes :

The vent hole change's :

original production-site UV glue sealing vent hole	new production-site hot sealing vent hole
 A photograph of a blue K7 DC type relay. A red circle highlights a small circular vent hole on the top surface of the relay, which is sealed with a clear, viscous substance (UV glue).	 A photograph of a white K7 DC type relay. A red circle highlights a small circular vent hole on the top surface of the relay, which is sealed with a clear, solid-looking substance (hot sealing).

The parts and fixing method changes :

original production-site	new production-site
	 <p data-bbox="1161 349 1366 501">增加加强筋 add rib reinforcement</p>
	<p data-bbox="831 689 1337 752">增加铆压固定 add riveting fixing</p> 
	<p data-bbox="815 1043 1342 1122">动簧形状变更 moving-spring's shape change</p> 
	<p data-bbox="810 1402 1286 1480">轭铁、衔铁形状变更 yoke's and armature's shape change</p> 

Part Number affected by these changes:

K7DPA05	K7DWA24	K7SWA05
K7DPA06	K7DWC05	K7SWA06
K7DPA09	K7DWC06	K7SWA09
K7DPA12	K7DWC09	K7SWA15
K7DPA15	K7DWC12	K7SWA18
K7DPA18	K7DWC15	K7SWC05
K7DPA24	K7DWC18	K7SWC06
K7DPC05	K7DWC24	K7SWC09
K7DPC06	K7SPA05	K7SWC12
K7DPC09	K7SPA06	K7SWC15
K7DPC12	K7SPA09	K7SWC18
K7DPC15	K7SPA15	K7SWC24
K7DPC18	K7SPA18	K7SPA12
K7DPC24	K7SPC05	K7SPA24
K7DWA05	K7SPC06	K7SWA12
K7DWA06	K7SPC09	K7SWA24
K7DWA09	K7SPC12	
K7DWA12	K7SPC15	
K7DWA15	K7SPC18	
K7DWA18	K7SPC24	

There will be impact on the form, fit or function of the part and no approval changes.

Anglia operates a strict FIFO system therefore it may take some time for this change to filter through to customer deliveries.

Please ensure this information is circulated to the relevant persons within your organisation

Yours Sincerely  
Anglia