

2<sup>nd</sup> March 2018

Dear Customer,

Anglia have been advised by the manufacturer OKO that the printing on the below relay families will be updated with immediate effect. Currently the parts are printed with electrical rating that match the datasheet specification, the printing is being updated to match the UL rating of the relays. OKO have confirmed there is no change to the form, fit and function of the relays. In addition, no changes have been made to the UL ratings or file number for the relays, the only change is the information printed on the relay itself.

Product affected by this notification:

|       |        |        |         |
|-------|--------|--------|---------|
| K1C03 | K1C03H | K1BE03 | K1BE03H |
| K1C05 | K1C05H | K1BE05 | K1BE05H |
| K1C06 | K1C06H | K1BE06 | K1BE06H |
| K1C09 | K1C09H | K1BE09 | K1BE09H |
| K1C12 | K1C12H | K1BE12 | K1BE12H |
| K1C24 | K1C24H | K1BE24 | K1BE24H |

Anglia operates a strict F.I.F.O system in our Distribution Centre therefore it may take some time for this change to filter through to customer deliveries.

Please ensure this information is circulated to the relevant persons within your organisation.

Yours Sincerely  
Anglia