

Modifications Notices

Automotive PCB Relay

Issue Date August, 2017

OMRON

No. ICN No. Dr-P-1772508

.

Product marking change due to manufacturing location change.

[Effective Date]

Effective as of our production in April, 2018.

[Applicable Model]

Model G8NW Series

< Refer to the " [Details of applicable model] " . >

[Reason for change]

Recently G8NW demands are decreasing and we have been gathering to appropriate locations.

[Change of products specification]

No

[Changes]

Before the change	After the change
OMRON RELAY & DEVICES Corporation, lida Factory (lida city, Nagano pref., Japan) Production line #1	SHANGHAI OMRON CONTROL COMPORNENTS CO.,LTD (Shanghai,China)
	Identification / Case marking
	Country origin (JAPAN -> CHINA DAPAN 198012 Configuration of lot code is not changed.
	Lot Code Configuration <u>19 8 0 1 2</u> 2: Working shift 1(day) or 2(night) 1: Line #1 0: Year (2010) 8: Month <19, X:Oct. Y:Nov. Z:Dec.> 19: Day I

*This document had been distributed by Omron Electronic Components Europe BV.

[Details of applicable model]

Models	OC CODE
G8NW-2H DC12 SK	G8NW1018M

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.