

## Product change notification (PCN)

<b>Title / short description</b>	Change of color for SH (M23 HYBRID) and SB (M40 HYBRID) series signal insulating bodies
<b>Affected article category</b>	Connectors
<b>Change category</b>	Form and appearance
<b>Change number</b>	CAB200078-01

### Purpose/objective of the change

Safeguarding availability

### Detailed description of the change

Due to a short-term material change at the supplier, the color of the signal contact carriers and insulating bodies in the SH (M23 HYBRID) and SB (M40 HYBRID) series has changed from rusty red to black. The change therefore only affects versions with unshielded signal inserts. Versions with CAT5 data inserts are unaffected by this change. The change of color has no effect on the product's technical characteristics. This change is with immediate effect.

### Identifying characteristics

Color of the signal insulating bodies

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	-
<b>Effective date (EOP)</b>	2020-09-01	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	-		

### Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input checked="" type="checkbox"/> Others          |   |  |

Short-notice material change by the sub-suppliers

### Attachments

- CAB200078\_pictures.pdf
- Material\_list.csv
- PCN-CAB200078-01 Farbänderung der Signalisierkörper der Serie SH (M23 HYBRID) und SB (M40-Hybrid)\_DE
- PCN-CAB200078-01 Change of color for SH (M23 HYBRID) and SB (M40 HYBRID) series signal insulating bodies\_EN

### Material list

Item	Article Type	Hardware / Firmware		Item	Substitute item Type
		old	new		
1028582	K-8E-M23M8/5,0-H01/M23M8-S4-S	0	1		
1096282	SH-8ESS48AY000S	0	1		
1096286	SH-8EPS48AY000S	0	1		
1105933	SBK-0534	0	1		
1105936	SHK-0535	1	2		
1621524	SH-8ESS48A8LDLS	1	2		
1621525	SH-8ESS48A8LB4S	1	2		
1621526	SH-8ESS48A8LB3S	1	2		
1621527	SH-8ESS48A8LB2S	1	2		
1621528	SH-8ESS48A8LB1S	1	2		
1621534	SH-8EPS48A8LDLS	1	2		
1621535	SH-8EPS48A8LB4S	1	2		
1621536	SH-8EPS48A8LB3S	1	2		
1621537	SH-8EPS48A8LB2S	1	2		
1621538	SH-8EPS48A8LB1S	1	2		
1621544	SH-8ESS48A9LDLS	0	1		
1621545	SH-8ESS48A9LB4S	0	1		
1621546	SH-8ESS48A9LB3S	0	1		
1621547	SH-8ESS48A9LB2S	0	1		
1621548	SH-8ESS48A9LB1S	0	1		
1621554	SH-8EPS48A9LDLS	0	1		
1621555	SH-8EPS48A9LB4S	0	1		
1621556	SH-8EPS48A9LB3S	0	1		
1621557	SH-8EPS48A9LB2S	0	1		
1621558	SH-8EPS48A9LB1S	0	1		
1621560	SH-8ESS48AAC00S	0	1		
1621562	SH-8EPS48AAC00S	0	1		
1621564	SH-8ESS48AAD00S	0	1		
1621566	SH-8EPS48AAD00S	0	1		
1621568	SH-8ESS48AWA00S	2	3		
1621570	SH-8EPS48AWA00S	2	3		
1622002	SH-8ESS48A8LDL	0	1		
1622003	SH-8ESS48A8LB4	0	1		
1622004	SH-8ESS48A8LB3	0	1		
1622005	SH-8ESS48A8LB2	0	1		
1622006	SH-8ESS48A8LB1	0	1		
1622012	SH-8EPS48A8LDL	0	1		
1622013	SH-8EPS48A8LB4	0	1		

Item	Article Type	Hardware / Firmware		Item	Substitute item Type
		old	new		
1622014	SH-8EPS48A8LB3	0	1		
1622015	SH-8EPS48A8LB2	0	1		
1622016	SH-8EPS48A8LB1	0	1		
1623329	SB-8ESSA8A8L32S	1	2		
1623330	SB-8ESSA8A8L33S	2	3		
1623331	SB-8ESSA8A8L34S	1	2		
1623335	SB-8EPSA8A8L32S	1	2		
1623336	SB-8EPSA8A8L33S	2	3		
1623337	SB-8EPSA8A8L34S	1	2		
1623344	SB-8ESSA8A9L32S	1	2		
1623345	SB-8ESSA8A9L33S	2	3		
1623346	SB-8ESSA8A9L34S	1	2		
1623359	SB-8EPSA8A9L32S	1	2		
1623360	SB-8EPSA8A9L33S	2	3		
1623361	SB-8EPSA8A9L34S	1	2		
1623366	SB-8ESSA8AA700S	1	2		
1623369	SB-8EPSA8AA700S	1	2		
1623372	SB-8ESSA8AWT00S	1	2		
1623375	SB-8EPSA8AWT00S	1	2		
1623686	SB-8ESSD8A8L32S	1	2		
1623687	SB-8ESSD8A8L33S	2	3		
1623688	SB-8ESSD8A8L34S	1	2		
1623695	SB-8EPSD8A8L32S	1	2		
1623696	SB-8EPSD8A8L33S	2	3		
1623697	SB-8EPSD8A8L34S	1	2		
1623704	SB-8ESSD8A9L32S	1	2		
1623705	SB-8ESSD8A9L33S	2	3		
1623706	SB-8ESSD8A9L34S	1	2		
1623713	SB-8EPSD8A9L32S	1	2		
1623714	SB-8EPSD8A9L33S	2	3		
1623715	SB-8EPSD8A9L34S	1	2		
1623720	SB-8ESSD8AA700S	1	2		
1623723	SB-8EPSD8AA700S	1	2		
1623726	SB-8ESSD8AWT00S	1	2		
1623729	SB-8EPSD8AWT00S	1	2		
1624251	SBK-0481	1	2		
1624307	K-8E-M23M8/2,0-H01/M23M8-S4-S	0	1		
1627071	SHK-0477	2	3		
1627204	SH-8ESS48AH000S	0	1		

Item	Article Type	Hardware / Firmware		Item	Substitute item Type
		old	new		
1627206	SH-8EPS48AH000S	0	1		
1627236	K-8E-M23M8/10,0-H01/M23M8-S4-S	0	1		
1628134	KSH11SP8813A005	0	1		
1628134	KSH11SP8813A005	0	1		
1628136	SHK-0504/02,50	2	3		
1628137	SHK-0505/01,00	2	3		
1629269	SH-8EPS48A0000-WPE/0030	0	1		
1629270	SH-8ESS48A0000-WPE/0030	0	1		
1028619	SHK-0478/30,00	0	1		
1162187	SHK-0542/05,00	0	1		
1211087	SHK-0548/01,30	0	1		
1162181	SHK-0541/05,00	0	1		
1161941	SHK-0478/10,00	0	1		
1624249	SBK-0482/05,00	0	1		
1027472	SB-8EP0A8A8L33S	2	3		
1627077	SH-8EP008A8LDLS	0	1		
1068265	SBK-0525/01,50	0	1		
1068259	SHK-0524/01,50	0	1		
1068166	SH-Z0078/SET	0	1		
1028590	SBK-0482/30,00	0	1		
1162147	SHK-0539/30,00	0	1		
1627074	SHK-0478/05,00	0	1		
1148354	SHK-0537/10,00	0	1		
1627076	SB-8EP0A8A8L34S	1	2		
1211079	SHK-0546/01,30	0	1		
1211080	SBK-0547/01,30	0	1		
1162154	SHK-0540/10,00	0	1		
1162126	SBK-0482/10,00	0	1		
1068164	SB-Z0003/SET	0	1		


OLD revision socket insulation body




NEW revision socket insulation body




OLD revision pin insulation body



NEW revision pin insulation body



OLD revision contact insert



NEW revision pin contact insert

