

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|----------------|-----------------|--------------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 02 | 007 | 003 | 0000002298 | See list below | Appliance inlet | 4798 | |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)



| List of part numbers affected | | | | | | | |
|-------------------------------|-----------|-----------|--|--|--|--|--|
| 4798.9000 | 4798.9100 | 4798.9200 | | | | | |

2 Type of change

Change of marking.

3 Detailed description of change

The part number is no longer printed on the product.

| Old product appearance | New product appearance |
|---|---|
|  |  |

4 Reason of change

Part number on product for identification not longer required.

5 Release date

The change will be rolled-out starting ww 06/2017 (Date code 1706 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

| | | |
|---------------|-----|----------------------------------|
| Form | Yes | Change of lettering |
| Fit | No | No change for dimension |
| Function | No | No change in function |
| Manufacturing | No | No change for manufacturing site |
| Label | No | No change on label |
| Packaging | No | No change in packaging |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|---------------------------------|---------|
| Data Sheet 4798 | |

| Product Change Notification | | | | | PCN 4798 | | |
|-----------------------------|---------------|--------------|-------------|-----------------|----------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-009-969 |
| hotzar | 2016-10-20 | 2017-02-08 | buerglal | 2011292 | A | 1 of 1 | |