

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	002	0000000500	See list below	Fuseholder complete	FPG1	n.a.

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)


List of part numbers affected

FPG1 complete				
3101.0010	3101.1010	3101.0110	3101.0110.02	3101.0015
3101.0115	3101.0011	3101.0111	3101.0210	3101.0310
3101.0215	3101.0315			
FPG1 socket				
3101.1511.1	3101.1511.2	3101.1513.1		
FPG1 carrier				
3101.7011	3101.7012	3101.7022	3101.7021	3101.7511
3101.7521				

2 Type of change

- Change of markings

3 Detailed description of change



4 Reason of change

- Newly approved nominal voltage according to IEC 60127-6

5 Release date

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form	Yes	Modified marking on product
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification					FPG1 change of the marks		
owner	creation date	release date	released by	change order no	rev	page	D10-010-914
zbindeja	2016-11-16	2017-01-30	nowakfr	2011481	A	1 of 1	