

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	010	0000000504	See list below	Fuseholder complete	FPG5	n.a.

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

### List of part numbers affected

#### FPG5 complete

3101.0050	3101.0055		
-----------	-----------	--	--

#### FPG5 socket

3101.5015.1			
-------------	--	--	--



#### FPG5 carrier

3101.8011	3101.8012	3101.8511	
-----------	-----------	-----------	--

## 2 Type of change

- Change of markings

## 3 Detailed description of change

Old product appearance	New product appearance
	

## 4 Reason of change

- Newly approved nominal voltage according to IEC 60127-6

## 5 Release date

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

## 6 Impact of change and recommended action

Form	Yes	Modified marking on product
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data Sheet</a>	

Product Change Notification						FPG5 change of the marks	
owner	creation date	release date	released by	change order no	rev	page	D10-010-919
zbindeja	2016-11-16	2017-01-30	nowakfr	2011481	A	1 of 1	